WASHINGTON DEPARTMENT OF ECOLOGY

ENVIRONMENTAL ASSESSMENT PROGRAM

FRESHWATER MONITORING UNIT

STREAM DISCHARGE TECHNICAL NOTES

STATION ID: 35M100

STATION NAME: Deadman Creek near Gould City

WATER YEAR: 2012

AUTHOR: Mitch Wallace

Introduction

Watershed Description

Deadman Creek is a left-bank tributary to the Snake River, opposite Central Ferry State Park. The creek drains the fertile agricultural highlands flanking the southern breaks of the Snake River in its northernmost bend into Washington State.

Gage Location

The station is located on the right side of the stream at the Deadman Creek road bridge, approximately 2.0 miles downstream from the confluence of the north and south forks of Deadman Creek.

Table 1. Basin Area and Legal Description

Drainage Area (square miles)	77 (USGS)
Latitude (degrees, minutes, seconds)	46° 36' 0" N
Longitude (degrees, minutes, seconds)	117° 36' 0" W

Table 2. Discharge Statistics.

Mean Annual Discharge (cfs)	4.5
Median Annual Discharge (cfs)	4.3
Maximum Daily Mean Discharge (cfs)	11
Minimum Daily Mean Discharge (cfs)	0.80
Maximum Instantaneous Discharge (cfs)	16
Minimum Instantaneous Discharge (cfs)	0.50
Discharge Equaled or Exceeded 10 % of Recorded Time (cfs)	6.8
Discharge Equaled or Exceeded 90 % of Recorded Time (cfs)	2.1
Number of Days Discharge is Greater Than Range of Ratings	17
Number of Days Discharge is Less Than Range of Ratings	0
Number of Un-Reported Days	40
Number of Days Qualified as Estimates	97
Number of Modeled Days	0

Note: Statistics displayed in Table 2 may not include values in which the predicted discharge exceeds the range of ratings.

Table 2 Discussion (Discharge Statistics)

The unreported days can be attributed to rating curve exceedances and data which were deemed to be unreliable.

Table 3. Error Analysis Summary.

Potential Logger Drift Error (% of discharge)		
Potential Weighted Rating Error (% of discharge)		
Total Potential Error (% of discharge)	28.0	

Table 3 Discussion (Error Analysis)

The potential logger drift error is a result of the mean daily flow difference between corrected and uncorrected data being greater than 20%.

Table 4. Stage Record Summary

Minimum Recorded Stage (feet)	4.75
Maximum Recorded Stage (feet)	5.43
Range of Recorded Stage (feet)	0.68

Table 4 Discussion (Stage Record)

The terminal end was buried in silt. Portions of the data were deemed as unreliable due to the silt build-up in channel.

Table 5. Rating Table Summary

Rating Table No.	14	112	15
Period of Ratings	10/1/11 to 10/17/11	10/1/11 to 2/1/12	1/25/12 to 5/21/12
Range of Ratings (cfs)	0.13 to 19	0.20 to 12	0.01 to 19
No. of Defining Measurements	1	8	3
Rating Error (%)	8.5	12.0	9.4
Rating Table No.	121		
Period of Ratings	5/20/12 to 9/30/12		
Range of Ratings (cfs)	0.14 to 8.7		
No. of Defining Measurements	11		
Rating Error (%)	12.6		
	T		
Rating Table No.			
Period of Ratings			
Range of Ratings (cfs)			
No. of Defining Measurements			
Rating Error (%)			

Table 5 Discussion (Rating Tables)

This site is susceptible to leaf litter accumulation on the control in the fall and early winter.

Table 6. Model Summary

Model Type (Slope conveyance, other, none)	n/a
Range of Modeled Stage (feet)	n/a
Range of Modeled Discharge (cfs)	n/a
Valid Period for Model	n/a
Model Confidence	n/a

Table 6 Discussion (Modeled Data)

Model was not used.	
---------------------	--

Table 7. Survey Type and Date (station, cross section, longitudinal)

Type	Date
Sta., X-section, Long.	10/17/2011

Table 7 Discussion (Surveys)			
Activities Completed			

Appendix